

**Onsite Laboratory Results Sheet**  
**Mobile Laboratory 2**

**Client:** ERM  
**Location:** Raytheon Site, Wayland, MA  
**Project ID:** Groundwater Profiling  
**SEI #:** 03-1473-R  
**Date(s) Sampled:** 5/11/2005  
**Date(s) Analyzed:** 5/11/2005  
**Test Method:** ASTM D6520 - SPME/GC  
**Report Date:**

**Matrix:** WP  
**Results Given as:** ug/L

**Profile ID:** B-547

Depth:		0.00		19.20		20.50		20.50		22.30		24.50			
Analysis Date/Time:	CAS#	5/11/05 16:08	EB	5/12/05 8:31	N	5/12/05 9:18	N	5/12/05 9:49	FD	5/12/05 10:42	N	5/12/05 10:42	N		
Vinyl Chloride	75-01-4	10 U	1	10 U	1	10 U	1	120 U	12	10 U	1	10 U	1		10 U
t-Dichloroethene	156-60-5	3 U	1	3 U	1	3 U	1	36 U	12	3 U	1	3 U	1		3 U
c-Dichloroethene	156-59-2	3 U	1	3 U	1	26	1	36 U	12	32	1	3 U	1		3 U
Trichloroethene	79-01-6	3 U	1	330	1	4020	12	4230	12	3190	12	180	1		3 U
Tetrachloroethene	127-18-4	3 U	1	3	1	33	1	58	12	18	1	3 U	1		3 U
SS Recovery		97	DF	98	DF	95	DF	94	DF	94	DF	90	DF		DF

U = Undetected below the specified reporting limit.

J = Estimated value.